

Date: - 05/01/22 ✓

STRUCTURAL STABILITY CERTIFICATE

On being requested by the School management, I inspected the existing school building of **Nirmal Public School**, at Kh no. 28/18, Nagpur Road Shikarpur, Teh. Chhindwara, District Chhindwara (M.P.)

B Building is R.C.C. frame structures, about 11 years old. But the buildings have been kept in immaculate condition by doing proper periodical maintenance.

There are no cracks of any other signs indicating a differential or otherwise structural settlement of any other problems.

The flooring is also in proper level. The rainwater management is proper. There are no obvious signs of water seepage in the building walls or ceiling.

The sanitary, plumbing and electrical fittings and fixtures are maintained in good condition.


The R.C.C. structure is in good condition and there is no visible damage to the columns, Beams or Roof slabs.

D We hereby certify that the school building is in good condition and structurally stable to the best of my judgment.

Hence this certificate.

Self Attested


PRINCIPAL
NIRMAL PUBLIC SCHOOL
VILL. SHIKARPUR, NAGPUR ROAD
CHHINDWARA (M.P.)


U.S. Parte
Sub. Engineer
Janpad Panchayat Mohkhed
Chhindwara (M.P.)